

RPM CT 110




- > On/Off/Esc
CT110 가
- > RPM




가

- > Hold/min/max
Hold 가
- > On/Off/Esc


- > Hol/min/max RPM / , Hol/min/max
- > On/Off/Esc /




- > 가 (/)
- > Select PROBE 가
- > OK PROBE (/) 가
- > Select OPTIC CONT 가
- > OK PROBE 가
- > On/Off/Esc




- > 가 , UNIT 가
- > OK 가
- 가 : tr/min, rpm, m/min, in/min, ft/min or m/s.
- 가 : tr/min or rpm.
- > OK
- > UNIT 가
- > On/Off/Esc



- > AUTO OFF 가 Select
- > AUTO OFF OK
- > Select 가 : 15, 30, 45, 60, 75, 90, 105, 120, OFF
- > OK
- > AUTO OFF 가
- > On/Off/Esc



- > Select , BEEP 가
- > OK
- > OFF ON
- > Select , ON , OFF
- > OK
- > BEEP 가
- > On/Off/Esc



- > [Light Icon] 가
- > [Light Icon] 가
- > [Light Icon] 가

- > AAA LR03 1.5 V.
- > 가



Once returned to KIMO, required waste collection will be assured in the respect of the environment in accordance to 2002/96/CE guidelines relating to WEEE

www.kimo.fr

EXPORT DEPARTMENT
Boulevard de Beaubourg - Emerainville - BP 48
77312 MARNE LA VALLEE CEDEX 2
Tel : + 33.1.60.06.69.25 - Fax : + 33.1.60.06.69.29

